

EDMS *Reference Manual* Supplement

-Model Changes Between EDMS 3.22 and EDMS 3.23-

January 3, 2001

User-Created Aircraft

| Change | Effect |
|---|--|
| <p><u>Time in Mode Calculation</u> In previous versions, there was a bug that caused user-created aircraft included in a study to not automatically update their approach and climb out times in mode after the mixing height was changed. This bug does not apply to system aircraft included in the study, since when the mixing height changed; the times in mode were adjusted.</p> | <p>The user can now change the mixing height after a user-created aircraft has been added to the study and the times in mode will be appropriately adjusted.</p> |

Reports

| Change | Effect |
|---|--|
| <p><u>Print All Model Inputs...</u> A label for the aircraft section of this report has been added.</p> | <p>This label was unintentionally omitted in previous versions. Now each section of input data is labeled.</p> |